



Egde R0.3 by
polishing all
the way around.




① 2 pcs.

2x Egde R0.3 by
polishing all the
way around.



②



③

